


Stage report, walls open, visit 2 of 3


2140 Sample Ave (sample). Scanned Apr 18, 2026, 9:10 AM. Tour link: provided on delivery.

Project	Scanned	Stage	Photos
2140 Sample Ave (sample)	Apr 18, 2026, 9:10 AM	Walls open, visit 2 of 3	112 in the full record; 3 shown in this sample

Location	Recorded	Page
1. Kitchen, sink wall	Drain and supply lines, before insulation.	Page 2
2. Laundry passage	Wiring run to the panel.	Page 3
3. Living room, east wall	Duct run above the header.	Page 4




1. Kitchen, sink wall



2. Laundry passage



3. Living room, east wall



Key plan: where each photo was taken (sample)

Each page shows the scan date and time. The photo files and the 3D tour link come with this PDF, in the project folder.

1. Kitchen, sink wall



- ① Studs
- ② Drain
- ③ Hot and cold supply

Location

Kitchen, sink wall

Recorded


Drain and supply lines, before insulation.

Stage

Walls open, before insulation and drywall


Scan date

Apr 18, 2026, scan started 9:10 AM



Key plan: photo 1

2. Laundry passage



Location

Laundry passage

Recorded


Wiring run to the panel.

Stage

Walls open, before insulation and drywall

Scan date

Apr 18, 2026, scan started 9:10 AM



Key plan: photo 2

3. Living room, east wall



Location

Living room, east wall

Recorded


Duct run above the header.

Stage

Walls open, before insulation and drywall

Scan date

Apr 18, 2026, scan started 9:10 AM



Key plan: photo 3